

1. Process gas
2. Cutting nozzle
3. Nozzle offset
4. Cutting speed
5. Molten material
6. Dross
7. Cut roughness
8. Heat affected zone
9. Kerf width

IKUSASA®

CNC TRAINING CENTRE

WE ARE THE FUTURE

G-CODE

ADVANCED TURNING

www.ikusasatraining.co.za

G-CODE COURSES

Advanced G-Code Turning

Requirements: Completion of Intermediate-Code Tuning is essential.

Duration: 3 Days

Time: 08:30 – 16:00

inclusions: Catering & Refreshments (full time inhouse training), relevant stationary, competency certificate, Machine Control Presentation, Training Manual (theory), Fanuc Control, Simulator Software, Tooling – Feeds & Speeds, Mathematics sets.

OVERVIEW

Our advanced course delves deeper into the complex mathematics associated with programming in the Turning environment. It provides an in-depth exploration of advanced trigonometry. Upon finishing this course, participants will be equipped to write and accurately calculate programs.

The course consists of 3 days in-class where we cover the complete basics in terms of:

- Trigonometry
- Fanuc Control simulator software
- In-class tests – sub-programmes
- Advanced cycles